









Lot #	Description	Manufacturer	Model #	Serial #	AG #	picture	condition/notes	price
1	tractor mounted spreader	Lely	BUDGET	8309 90731			works, not used in years	200
2	tractor mounted flail mower	Woods	T42		v.old 593153		works, not used in years	100
3	tractor mounted finishing mower	Woods	RM48				belt issues	75
4	back hoe with front bucket/early'90	John Deere	310D		0002472107		runs, needs lots of work, fair	9,500
5	trailer hitch soil cart	Lindig	TC-848	25982			fair to good, flat tires	100
6	mini truck #8	Cushman	898615		0082052988		needs work, fair to poor	100
7	mini truck #13	Cushman	898615		0002753369		missing 2 tires, fair to poor	50
8	mini truck #21	Cushman	898615		0002753074		needs work, fair to poor	75
9	mini truck #9	Cushman	898615		0002753077		needs work, fair to poor	100
10	mini truck #28	Tiger			0002283034		poor, bed not attached	50
11	mini truck #26	Tiger			0002283050		poor	50
12	riding mower-zero turn	John Deere			0002753179		drive belt broken, runs otherwise	1,000
13	riding mower-zero turn	John Deere	997		0002753332		runs, tends to stall	1,500
14	vehicle trailer						decking rotted/?roadworthy?	

15	walk behind tiller	Troy Bilt (Horse)	176437			unknown, not used in many yrs	50
16	3 gallon backpack sprayer	Solo				leaks	50
17	Rereciprocating weed wacker	Redmax	G2KC			does not start,teeth broken	20
18	Weed Wacker	Kowasaki	KGT27B			pull cord too short,carb trouble	20
19	Weed Wacker	Echo	SRM 230			Carb trouble, missing parts	20
20	Weed Wacker	Echo	SRM 261			Carb trouble, missing parts	20
21	backpack leaf blower	Stihl	BR550			fuel tank leaks,unused in yrs	50
22	backpack leaf blower	Echo	PB 770T			carb trouble, needs a rebuild	50
23	backpack leaf blower	Echo	PB 770T			carb trouble, needs a rebuild	50
24	push mower	Snapper	commerical			Brigs engine	30
25	push mower	Toro				Brigs engine 8.5 hp	30
26	push mower	Husqvarna				Honda engine	30
27	walk behind tiller	Troy Bilt (Horse)	GH17/TH1019			runs, needs tire	50
28	push mower	Craftsman	Gold			does not start	30
29	Weed Wacker	Stihl	FS 130R			does not start	20

